

## Deck Rebuild




All the stringers were rotted and had to be replaced







Layout for new deck using Trex decking





New 2X8 pressure treated stringers set on pavers



Done