
## **Bathroom Remodel at the old Doubletree House**




Had to tear out the cracked tile and dripping plumbing







The studs in the wall around the window were rotted and the wall would need to be rebuilt.



## Going with glass block windows when I rebuilt the wall would mitigate the water getting in the wall.



## Time for the new plumbing





I went with the one piece unit that had to go in through the wall In the upstairs closet.



Next the walls and the trim





**Done**