

Living Room Window Project



The seal had deteriorated letting moisture in between the glass



New window ready for installation





Outside Trim
painted sealed
and installed
on new window
6-17-04





Done

